prado

light + motion | surface 2.0
installation instruction


1






Turn the power off.

2




Fix the mounting plate on the ceiling with appropriate screws.

3




Tighten the wires through the strain relief and cut off the excess wire.

4




Connect the wires with wago connectors for parallel connection, respect polarity. Combine with a prado LED-driver.

5



The potential-free contact closes when the luminaire turns on.

6




Click the luminaire onto the connection plate.

7



Turn the power back on. The luminaire will turn on when the ambient light is low enough and movement is detected. After the last detection of movement, the luminaire will stay on for 5 minutes. These are default settings and cannot be adjusted.

8



For maintenance, the luminaire can gently be removed from the ceiling.

thank you for choosing prado

prado.com

The light source or electronics in this fixture shall only be replaced by the manufacturer. Warranty will not apply in case of wrongful use or if unskilled personnel attempts to repair the product.