
prado


clt ring Ø57
installation instruction

1




Mill a round hole with the above dimensions. Consult the chosen luminaire tech specs for required height and free air dimensions.

2




place the clt ring in the hole, black side facing down

3



fixate the ring to the clt with the appropriate glue

4



the fixture can now be installed

thank you for choosing prado

prado.eu

Installation must be done by skilled professionals only and instructions must be followed at all times. Warranty will not apply in case of wrongful use of if unskilled personnel attempts to repair a product.