
empty floor box Ø60
installation instruction

for **concrete workfloor** go to page 2 (click here)


for **tiles** go to page 13 (click here)



heating system



isolation with technics




concete workfloor

Choose your type of floor.

1

concrete workfloor




Build up all floor layers except the top concrete layer. Leave an opening of at the location on the floor socket.

2


optional floor box level support

floor box level support - installation




version	product number	dimensions
single	8800-2525	100 x 100 mm
double	8800-2526	200 x 100 mm

3




Fill the hole with screed.




Insert preflex in the floor box - cabling through bottom.

5




Insert the floor box in the screed and level the top of the box.




Build up the final concrete layer.

7




Gently remove the plaster lid.

8




Connect the socket (not incl.) and click it in the holder. Compatible with trimless retro-/backfit type E/F socket modules.

9




Insert the showring.

10



Install the cover plate Ø60 of choice (sold separately).


11



For access, remove the cover plate with a plug.

1

tiles




Build up all floor layers except the tiles layer. Leave an opening of at the location on the floor socket.


2

optional floor box level support


floor box level support - installation



version	product number	dimensions
single	8800-2525	100 x 100 mm
double	8800-2526	200 x 100 mm




Fill the hole with screed.




Insert preflex in the floor box - cabling through bottom.

5




Insert the floor box in the screed and level the top of the box.

6




Build up the final layers of the floor.

7




Gently remove the plaster lid.

8




Connect the socket (not incl.) and click it in the holder. Compatible with trimless retro-/backfit type E/F socket modules.

9




Insert the showring.

10



Install the cover plate Ø60 of choice (sold separately).

11



For access, remove the cover plate with a plug.

thank you for choosing rond

Installation must be done by skilled professionals only and instructions must be followed at all times. Warranty will not apply in case of wrongful use or if unskilled personnel attempts to repair a product.